

MICHI

Technical Service Bulletin

Nov 3, 2020

P5 - Version 1.12 Software Release

The P5 software has been updated and includes bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.12
Previous Version	V1.09

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	255-043-1080

Release Notes
<ul style="list-style-type: none">• Improved the software upgrade recovery mechanism to enhance robustness.• Fixed a bug where the Volume knob stayed active in Standby mode.• Implemented Auto Mute function. This function will mute the output when no audio was detected for 30 seconds to eliminate noise. Note that this function will be set to ON by default after software update. Note that this function can be disabled by navigating the SETUP menu to "AUDIO - AUTO MUTE" setting.• Other minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --

MICHI

Technical Service Bulletin

May 8, 2020

Michi P5 - Version 1.09 Software Release

The Michi P5 software has been updated to Version 1.09. This release includes bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.09
Previous Version	V1.05, V1.08

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	255-010-1050

Release Notes
<ul style="list-style-type: none">• Fixed a bug in the Balance setup.• Improved the robustness of the Software Upgrade function eliminating a bug that sometimes occurs at 99% download in Software V1.07.• Enhanced support for different manufactures of the USB flash drives in Software V1.07.• Improved the robustness of the Software Upgrade function eliminating a bug where a white screen sometimes occurs at 99% download in Software V1.07. <p>Note: If you encounter a white screen error at 99% download during upgrade, please reboot the unit via the POWER switch on the back panel and try to upgrade again.</p> <ul style="list-style-type: none">• Optimized the gain strategy to eliminate potential noise in Software V1.08.• Improve the software upgrade process to eliminate failed upgrades in Software V1.08.• Other minor bug fixes and enhancements.

For more information or questions please contact your customer service representative.

-- End --


MICHI

Technical Service Bulletin

Nov 22, 2019

Michi P5 - Version 1.05 Software Release

The Michi P5 software has been updated to Version 1.05. This release includes bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V1.05
Previous Version	V1.03

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Silver	255-938-1050

Release Notes
<ul style="list-style-type: none">• Minor bug fixes and improvements.
<ul style="list-style-type: none">• Added a Space key to the Custom Name keyboard for better user experience.
<ul style="list-style-type: none">• Fixed a bug where the action of commands “bypass_on!” and “bypass_off!” is in reverse.

For more information or questions please contact your customer service representative.

-- End --

MICHI

Technical Service Bulletin

Oct 18, 2019

Michi P5 - Version 1.03 Software Release

The Michi P5 software has been updated to Version 1.03. This release includes bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.03
Previous Version	V1.02

Serial Number (Change will be effective in units starting with the serial numbers listed below.)	
Black	255-929-1001

Release Notes
<ul style="list-style-type: none">• Fixed a bug volume was not reduced to preset power on volume after a reboot.
<ul style="list-style-type: none">• Fixed a bug network connection was terminated when using Network Wakeup function.
<ul style="list-style-type: none">• Fixed a bug incorrect direction of increasing/decreasing the level of Bass and Treble using the IR remote control.
<ul style="list-style-type: none">• Fixed a bug incorrect sample rate occurs on the display when switching tracks during playback.
<ul style="list-style-type: none">• Fixed a bug incorrect feedback of some RS232 commands

For more information or questions please contact your customer service representative.

-- End --