

# MICHI

## Technical Service Bulletin

Oct 25, 2021

### X3 – Version 1.05 Software Release

The X3 software has been updated to include bug fixes and improvements as listed below.

#### Release Type

|  |       |          |
|--|-------|----------|
|  Maintenance | Major | Critical |
|--|-------|----------|

#### Software Information

|                  |       |
|------------------|-------|
| New Version      | V1.05 |
| Previous Version | V1.04 |

#### Serial Number (Change will be effective in units start from the serial numbers listed below.)

|       |              |
|-------|--------------|
| Black | 261-123-1001 |
|-------|--------------|

#### Release Notes

- Fixed a memory error to avoid reloading the max volume level after power cycle if the last volume level was higher than default value.
- Modified the default Max Volume level to 35.
- Added "AUTO MUTE" option to mute the output when no audio is detected.
- Improved online server update detection after manually renewing the DHCP IP address.
- Corrected a display error when changing from a Fixed Volume Source temporarily showing the fixed volume level.
- Added discrete Hex IR Remote codes for direct source selection.
- Optimized the volume curve for Phono stage.

*For more information or questions please contact your customer service representative.*

*-- End --*

## Technical Service Bulletin

Dec 24, 2020

### X3 - Version 1.04 Software Release

The X3 software has been updated to include bug fixes and improvements as listed below.

| Release Type |       |          |
|--------------|-------|----------|
| Maintenance  | Major | Critical |

| Software Information |       |
|----------------------|-------|
| New Version          | V1.04 |
| Previous Version     | V1.02 |

| Serial Number (Change will be effective in units starting from the serial numbers listed below.) |              |
|--|--------------|
| Black  | 261-045-1001 |

| Release Notes  |
|--|
| <ul style="list-style-type: none"><li>• Fixed a bug where crack noise could be heard when pausing DSD playback or switching DSD tracks. Note that PC-USB firmware was required to be updated to V1.01 to fix this bug.</li><li>• Modified the default Factory Reset Volume to 45.</li><li>• Fixed a bug where Power On Max Volume was set to 50 after a cold reboot when the preset value &gt; 50.</li><li>• Improved PC-USB Audio processing</li><li>• Other minor bug fixes.</li></ul> |

*For more information or questions please contact your customer service representative.*

*-- End --*

## Technical Service Bulletin

Dec 24, 2020

### X3 - Version 1.02 Software Release

The X3 software has been updated to include bug fixes and improvements as listed below.

| Release Type   |       |          |
|--|-------|----------|
|  Maintenance | Major | Critical |

| Software Information |       |
|----------------------|-------|
| New Version          | V1.02 |
| Previous Version     | V1.01 |

| Serial Number (Change will be effective in units start from the serial numbers listed below.) |              |
|---|--------------|
| Black   | 261-021-1001 |

| Release Notes  |
|--|
| <ul style="list-style-type: none"><li>•Modified power consumption based options.</li></ul> |

*For more information or questions please contact your customer service representative.*

*-- End --*