

## Technical Service Bulletin

Jan 24, 2022

### RSP-1576MKII - Version 3.07 Software Release

The RSP-1576MKII software has been updated to includes bug fixes and improvements as listed below.

| Release Type |       |          |
|--------------|-------|----------|
| Maintenance  | Major | Critical |

| Software Information |       |
|----------------------|-------|
| New Version          | V3.07 |
| Previous Version     | V3.06 |

| Serial Number (Change will be effective in units after the serial numbers listed below.) |              |
|--|--------------|
| Black  | 258-136-1150 |
| Silver   | 758-136-1050 |

| Release Notes   |
|---|
| <ul style="list-style-type: none"><li>● Implemented a warning message "The unit will automatically power off after the update is complete." at the end of upgrade.</li><li>● Enhanced software upgrade fault handling mechanism.</li><li>● Improved the consistency of internal generated test tone default level for manual room calibration as well as Dirac room calibration.</li><li>● Fixed a bug where unexpected erasure of Dirac profiles happened occasionally.</li><li>● Other minor bug fixes.</li></ul> |

*For more information or questions please contact your customer service representative.*

*-- End --*

## Technical Service Bulletin

October 22, 2021

### RSP-1576MKII – Version 3.06 Software Release

The RSP-1576MKII software has been updated to include bug fixes and improvements as listed below.

| Release Type |       |          |
|--------------|-------|----------|
| Maintenance  | Major | Critical |

| Software Information |       |
|----------------------|-------|
| New Version          | V3.06 |
| Previous Version     | V3.04 |

| Serial Number (Change will be effective in units after the serial numbers listed below.) |              |
|--|--------------|
| Black  | 258-113-1150 |
| Silver   | 758-113-1050 |

| Release Notes   |
|---|
| <ul style="list-style-type: none"><li>Supported new update MCU chipset.</li></ul> |

*For more information or questions please contact your customer service representative.*

*-- End --*

## Technical Service Bulletin

July 19, 2021

### RSP-1576MKII – Version 3.04 Software Release

The RSP-1576MKII software has been updated to include bug fixes and improvements as listed below.

| Release Type |       |          |
|--------------|-------|----------|
| Maintenance  | Major | Critical |

| Software Information |       |
|----------------------|-------|
| New Version          | V3.04 |
| Previous Version     | V3.03 |

| Serial Number (Change will be effective in units after the serial numbers listed below.) |              |
|--|--------------|
| Black  | 258-113-1150 |
| Silver   | 758-113-1050 |

| Release Notes   |
|---|
| <ul style="list-style-type: none"><li>• Improved the consistency of internal generated test tone default level in subwoofer for manual room calibration.</li><li>• Optimized the output level in subwoofer when engaged Dolby Atmos Surround or DTS Neural:X remixing mode, and loaded Dirac filter.</li><li>• Enhanced the reliability and inter-operability performance of when click [&gt;] play button to generate test tone in Dirac Live app.</li><li>• Improved Dirac calibrating performance in speaker distance.</li><li>• Fixed an error where there was no generated test tone from Height 1 and Height 2 pre-outputs when configured as "HIGH FRONT" or "HIGH REAR" speakers under x.x.2 audio system.</li><li>• Fixed an inconsistency error, to remove "OVERHEAD / HIGH" speaker configuration option from main menu under 5.1 or 7.1 audio system.</li><li>• Fixed a hiccups / stutters error when switching the digital audio stream from Dolby Digital "5.1" to "2.0".</li><li>• Fixed a 12V trigger function error, to avoid system accidentally powering on a 12V trigger connected amplifier when the unit enters standby mode.</li></ul> |

*For more information or questions please contact your customer service representative.*


-- End --

## Technical Service Bulletin

December 04, 2020

### RSP-1576MKII - Version 3.03 Software Release

The RSP-1576MKII software has been updated to include bug fixes and improvements as listed below.

| Release Type  |       |          |
|---|-------|----------|
|  Maintenance | Major | Critical |

| Software Information |       |
|----------------------|-------|
| New Version          | V3.03 |
| Previous Version     | V3.01 |

| Serial Number (Change will be effective in units after the serial numbers listed below.) |              |
|--|--------------|
| Black  | 258-030-1169 |
| Silver   | 758-030-1030 |

| Release Notes   |
|---|
| <ul style="list-style-type: none"><li>• Fixed a bug where the unit had no output when processing Dolby Atmos content from Netflix.</li><li>• Implemented Dirac mode forced exit by pressing the BACK remote key.</li><li>• Updated the text of Online Upgrade process for better clarity.</li><li>• Fixed a bug where the unit failed to indicate Dolby 5.1 content from Netflix in the Display menu.</li><li>• Fixed a bug regarding Bass Management.</li><li>• Fixed remixing bugs that could led to audio stutter or no output in several occasions.</li><li>• Fixed a bug where abnormal output level occurred after going back to the Runtime screen from Speaker Level Menu with a Analog source and Stereo surround mode selected.</li><li>• Fixed Dirac bugs that were triggered by the change of Audio System Configuration.</li><li>• Minor bug fixes related to Dirac function.</li><li>• Minor bug fixes related to the Setup Menu operation.</li></ul> |

*For more information or questions please contact your customer service representative.*

-- End --