

# Technical Service Bulletin

November 12, 2020

## RCD-1572 - Version 2.37 Software Release

The RCD-1572 software has been updated including bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.37
Previous Version	V2.33

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	251-046-1001
Silver	751-030-1001

Release Notes
<ul style="list-style-type: none"><li>• Fixed a bug where the unit failed to close the CD tray completely when entering Standby mode.</li><li>• Fixed a bug where sometimes the unit failed to reload the CD left in the drawer after a warm power cycle.</li><li>• Fixed a bug where sometimes the unit failed to reload the CD left in the drawer after a 12V trigger power cycle.</li><li>• Fixed a bug where the system had no action when the user pressed PLAY or EJECT button during Standby.</li><li>• Fixed a bug where CD-Text was not updated when playing a CD without manually changing tracks.</li><li>• Fixed a bug where the system had no action when the user pressed PLAY or EJECT button during Standby.</li><li>• Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --

# Technical Service Bulletin - Updated

Mar 28, 2019

## RCD-1572 - Version 2.33 Software Release

The RCD-1572 software has been updated to Version 2.33. This release includes power consumption regulations as well as other bug fixes and improvements. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.33
Previous Version	V2.32

Serial Number (Change will be effective in units starting with the serial numbers listed below.)	
Black	251-829-1001
Silver	751-829-1001

Release Notes
<ul style="list-style-type: none"> <li>Changed the default value of OFF TIMER from DISABLE to 20 MINS to meet the power consumption regulations.  <i>Note that unit would enter STANDBY mode when the following conditions are fulfilled:</i> <ol style="list-style-type: none"> <li>Unit is in STOP state. (Pressing STOP key twice)</li> <li>No RS232 or ROTEL LINK communication</li> <li>No actions from remote control or front panel keys</li> </ol> </li> <li>Added OFF TIMER warning message display. Unit will display a blinking remaining-time message three times in the last three minutes, each for 5 seconds, and will display a static warning message in the last ten second.</li> </ul>

*For more information or questions please contact your customer service representative.*

*-- End --*