



Technical Information

DATE: July 17, 2015

Software Release Notes

The following document contains details of the updates for the front USB software, and the release notes are listed below.

Key:

New Feature

Feature Change

Bug Fix – Critical

Bug Fix – Minor

Front USB Software

V500BT to V507BT

July 17, 2015

- **Bug Fix (Minor):** Fixed a bug that could cause the unit to intermittently jump to the next track when playing audio from iOS devices with services such as Spotify or Tidal.
- **Bug Fix (Minor):** Corrected an issue that could cause the unit to eventually stop playing audio from an iPod Classic when playing from a very long playlist.

V1.12 to V5.00BT

May 15, 2013

Recommended Minimum Main Software: V1.15

- **Feature Change:** Updated the Authentication co-processor required to communicate with attached Apple iOS devices (iPad, iPhone, iPod).

V1.10 to V1.12BT

October 20, 2011

Recommended Minimum Main Software: V1.15

- **New Feature:** Added support for Bluetooth Streaming with a Rotel supplied Bluetooth Dongle.